






System Motor Ratings(230v)
 SG2195 - 0.6amp
 SG4960 - 0.6amp
 SG5800 - 2.2amp
 SG8600-0.66amp
 SG8640- 1 amp



Important
 Plug / socket must be wired correctly with exposed pins on SG9917 fitted to motor tail



Warning : BS6500 - Neutral in 4 core flexible cable is now coloured Grey (Previously Blue)



All printed & electronically distributed copies of this drawing are uncontrolled copies

Silent Gliss Ltd
 Poorhole Lane.
 Broadstairs
 Kent CT10 2PT
 Tel 01843 863571
 Fax 01843 864503
 E-mail: info@silentgliss.co.uk
 Web site: www.silentgliss.co.uk

2 or more Motors from 1 Switch Simultaneously
Systems SG2195, SG5800, SG8600, SG8640 (4960 K Series Motor)
 (Motors must not be wired directly in parallel.)
 System SG8960 requires individual control to ensure alignment of slats in banked blinds

Drawing Number
E 102
Issue Date 31/10/19 FRO